

Approved For Release 2002/10/25 : CIA-RDP74B00496R000200040029-2

IMMEDIATE**SECRET**

(When Filled In)

FILE IN

27 MAY 71 0840

C 157 C
27 MAY 71 0620

REPRODUCTION PROHIBITED

ACTION	1	6	11	16
	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	10	15	20

NNNS E C R E I 270559Z MAY 71 CITE [REDACTED]

25X1A

25X1A

25X1A

IMMEDIATE [REDACTED]

[REDACTED]

SUBJ: MISSION C-151C

LONG SHAFT SYST MALFUNCTION CAUSE HAS BEEN RESOLVED AND MISSION

GENERATION IS PROCEEDING. DEFICIENCY DISCOVERED IN K-5 RELAY IN

L/S A-3 RECEIVER ASSEMBLY. PROBLEM WAS DUPLICATED ON BENCH CHECK.

FYI TROUBLE INDICATION WAS LOSS OF LOG VIDEO AT 0344Z (MISSION C-141C).

GP-1

S E C R E T

BT

